KELLER

HIGHLY PRECISE DIGITAL MANOMETER

LEX 1 / LEX 1 Ei

19959

18962

KELLER

LEX 1

PRECISION**: 0,01 %FS / RS485 BUS INTERFACE

LEX 1 is a micro-processor controlled, accurate and versatile digital pressure measuring instrument with integrated Max.-/Min.-function for calibration and testing purposes. LEX 1 Ei is approved per IECEx for use in hazardous areas. Via the RS485 Bus Interface, communication with up to 128 connected instrument can take place.

The pressure is measured twice per second and displayed. The top display indicates the actual pressure, the bottom display shows the Max.- or Min.-pressure since the last RESET.

LEX 1 has two operating keys. The left key is to turn the instrument on, to select the functions and the pressure units. The right key executes the selected function resp. unit or serves to display the Max.- and Min.-value.

The instrument has the following functions

- RESET With the RESET-function, the Max.- and Min.-value is set to the actual pressure value.
- ZERO With the RESET-function, the Max.- and Min.-value is set to the actual pressure value.
- CONT The instrument turns off 15 Min. after the last key function. Activating CONT (Continuous) deactivates this automatic turn-off.
- UNITS All standard instruments are calibrated in bar. The pressure can be indicated in 13 different units.

Included with Delivery

Carrying case and 5-point calibration certificate.

Optional Accessories

LEX 1 Ei

Certifications File:

additional protection board.

the standard LEX 1 version.

Carrying bag, protective rubber covering, interface converter K-114A

Intrinsically Safe Version, 94/9/EG and IECEx

PTB 05 ATEX 2012 X and IECEx PTB 13.0028X

The intrinsic safe version of LEX 1 incorporates an

Functions, ranges and accuracy are identical to

Classification: 🕢 II 2 G Ex ia IIC T6 Gb



Display 5 Digit LEX 1

5-Point Calibration Certificate (included with delivery)

CE

18959

18.962 KELLER



Subject to alterations

10/2013



KELLER

Specifications

Pressure Ranges rel.										
PR	-0,30,3	-12	-110	-120						bar
Pressure Ranges abs.										
PA					0100	0200	0400	0700	01000	bar
PAA	00,3	03	011	021						bar
Overpressure	3	6	20	40	200	400	800	1100	1100	bar
Resolution Display	0,1	0,1	1	1	10	10	50	100	100	mbar
Resolution (pressure) via interface		0.0025 %FS								

PR = Vented Gauge. Zero at atmospheric pressure PA = Absolute. Zero at 1 bar abs. PAA = Absolute. Zero at vacuum

Number of Digits	5 Digit					
Accuracy *	0,05 %FS					
Total Error Band (050 °C)	0,10 %FS (Accuracy, incl. temperature error)					
Precision **	Standard 0,05 %FS					
	Optional for \ge 20 bar: 0,025 %FS or 0,01 %FS					
Storage- / Operating Temperature	-1060 °C / 050 °C					
Long Term Stability typ.	Vented Gauge: min. 1 mbar or 0,05 %FS					
	Absolute: min. 0,5 mbar or 0,025 %FS					
Compensated Temperature Range	050 °C					
Supply	3 V battery, Typ CR 2430					
External supply (excl. Ei instruments)	828 VDC					
Battery Life	2'000 hours continuous operation					
Pressure Connection	G1/4"					
Interface	RS485; rear-sided mating plug "Fischer"					
	compatible with PC-converter cable K103-A					
	(RS232) and K114-A (USB)					
Protection	IP 65					
Diameter x Height x Depth	76 x 118 x 42 mm					
Weight	210 g					

** Accuracy and Precision

"Accuracy" is an absolute term, "Precision" a relative term. Dead weight testers are primary standards for pressure, where the pressure is defined by the primary values of mass, length and time. Highest class primary standards in national laboratories indicate the uncertainty of their pressure references with 70 to 90 ppM or close to 0,01%.

Commercial dead weight testers as used in our facilities to calibrate the transmitters and manometers indicate an uncertainty or accuracy of 0,025%. Below these levels, KELLER use the expression "Precision" as the ability of a pressure transmitter or manometer to be at each pressure point within 0,01 %FS relative to these commercial standards.

The manometer's full-scale output can be set up to match any standard of your choice by correcting the gain with a calibration software.

* Includes Linearity + Repeatability + Hysteresis

CCS30

Pressure and temperature readings can be displayed and recorded on PC or Laptop with help of the software ControlCenterSeries30 (CCS30) and a seriel interface cable. The software also enables configuration of the zero point settings. The Keller-Bus protocol and programming examples in various programming languages are available. This allows very quick and easy implementation in customer software applications. Up to 128 devices can be connected together into a KELLER Bussystem.

